











too much air trapped in the elastomer

holes at functionally relevant areas

mold was opened too early