


File Options



Running 20140512_0956_05.nirs

DISPLAY

Display Window (seconds) 10

Y Range [min max] 10 150

Signal Min 60

Noise Thresh 0.05

Stim Mark

STOP

690 830

☐ Delta OD☒ Autoscale

Display Aux

Signal Max 120

Det Max 140

AUXILIARIES

<input checked="" type="checkbox"/>	Nothing	<input type="checkbox"/>	Nothing
<input type="checkbox"/>	Nothing	<input type="checkbox"/>	Nothing
<input type="checkbox"/>	Nothing	<input type="checkbox"/>	Nothing
<input type="checkbox"/>	Nothing	<input type="checkbox"/>	Nothing

SOURCES (690 830 nm)

A	1	2
B	3	4
C	5	6
D	7	8
E	9	10
F	11	12
G	13	14
H	15	16

All On/Off

DETECTORS

D1	D2	D3	D4	D5	D6	D7	D8
100	1	1	3	2	1	1	2

D17	D18	D19	D20	D21	D22	D23	D24
18	10	4	2	4	4	4	1

Auto Gain Level

Rate (Hz)

Set All Gains

Set Gain 110

50

1