







Figure 4: Steps of injection through a connector.

- A. Disinfect the surface of the connector for 3 seconds with 70% isopropyl alcohol. Insert the tip of the syringe or infuser through the connector.
- C. Inject or infuse the medication
- D. Remove the syringe or infuser