



Calibrate Aperture...

Verify Aperture Calibration...

Run Concentration Control...

Aperture Calibration Options...

Control Sample Options...

Load SOP...

Sample Information

File ID: Test

Sample ID:

Edit Info...

SOM

Control Mode: Total Count
125000Aperture: 100 μ m

Kd: 126.39

Current: 1600 μ A

Gain: 2

Runs: 1

Wait Time: 0 s

Save: Yes

Print: No

Export: Yes

Edit SOM...

Stirrer: Off 9.4°



Waste Tank



Waste Jar



Electrolyte Jar

